

Dry Dock No. l, 1928. Built in 1891, it leaked so badly during the l920s that it could not dock ships. Commandant Thomas P. Magruder's persistent request for repair contributed to his removal from command. NARA Washington, D.C., Still Picture Branch.